Report on Condition of Property considered for Minot Façade Improvement Program

Date of Walkthrough: Aug 17, 2021 Staff Present: Jonathan Rosenthal, Rick Walker, Luke Tillema

Owner/ Representatives Present: Andrew and McKenna Gudmunson

Others present: Pete Hugret, Josh Wolsky, Jason Bentley, Jen Cook

Business: 701 Realty Address: 24 First Street SE

Current Use: Business/Design Offices and Apartments

Summary: The building is in very good condition. Every unit is clean and in good condition. The building does not appear to present significant issues that would endanger health and safety or would lead to condemnation or demolition.

According to staff, is the building in suitable condition to apply? YES, pending a review of the roof.

Building footprint and related information

Stories: 2 plus basement. **Size**

Fire suppression: Yes

Alley Access: Yes Fire escape: No

Basement Conditions

Heating Plant condition/age Hot air/ Newer ductwork old boiler left in place

Air conditioning Yes

Moisture issues present None

Condition of support columns NA

Condition exterior walls/foundation Excellent

Storage Very clean. No clutter. Generally open and accessible.

First Floor

Ceiling:

Flooring: Carpet and vinyl

Freight or other elevator Freight/non-op

Stairways up and/or down 2 Width

Between railings 36 inches

Rooms (Number and type):4 apartments on this floor (to be converted to commercial)

Finish(es): Modern office in rear

Bathrooms: In each unit

Second Floor

Ceiling:	
Flooring:	Carpeted mostly.
Two or more means of egress	YES
Rooms (Number and type): commercial)	7 apartments, 4 apartments down (to be converted to
Windows	In each unit
Other features:	
Bathrooms:	In each unit
Third Floor and Fourth Floors NOT APPLICABLE	
Ceiling:	
Flooring:	
Two or more means of egress	
Windows	
Other features:	
Bathrooms:	
Roof	
Condition unknown but there are no visible areas or leaks through the ceiling or walls at present. There is some marking from previous leaks including a hole in the "tin ceiling" from rust/corrosion.	
Prospects for upper floor conversion:	

Disclaimer: This report was generated as a result of a walk-through inspection by city staff and board members for consideration to provide funding for improvements. It is not intended as a true building or safety inspection by the City of Minot or its Building, Community Development, Planning, Economic Development, or other departments. The building owner or tenant is not being provided with any assurance of either program funding or the condition of the building for purchase, sale, or life safety. It is the responsibility of the owner to secure qualified parties to perform such work

Already converted and in very good condition. Modern but modest single bedroom units with finishes that reflect that. No

amenities except for shared coin-operated laundry,

Residential units -Quick Assessment for possible use: